Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Wed 02/28/2024

Job#

Weather

6:00 AM

Wind: 18 MPH | Precipitation: .0" | Humidity: 53%

12:00 PM

Wind: 13 MPH | Precipitation: .0" | Humidity: 30%

4:00 PM

Partially cloudy

Wind: 11 MPH | Precipitation: .0" | Humidity: 23%

Work Logs

Description Name

Cavins Group Enviromental

Cavins technician assisted the Envelope Consultants with carrying and setting up of a ladder, with moving the boom lift, adding diesel fuel to boom lift, and with the Oklahoma Roofing company.

Total

General Notes

1. Equipment On Site



2. Oklahoma Roofing















3. The Boom Lift

























4. Envelope Consultants











5. Diesel Fuel 5 - Gallons





- **6.** Third Floor Main Area: Equipment 1 Air Scrubber

 - 1 50' Extension Cord
- 7. Second Floor Main Area: Equipment
 - 1 Air Scrubber
 - 1 25' Extension Cord
- 8. First Floor Main Area: Equipment
 - 3 Air Scrubbers
 - 1 25' Extension Cord