

# Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Tue 02/27/2024

Job #

## Weather

6:00 AM

64°

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 41%

12:00 PM

74°

Clear

Wind: 17 MPH | Precipitation: .0" | Humidity: 33%

4:00 PM

79°

Partially cloudy

Wind: 17 MPH | Precipitation: .0" | Humidity: 28%

## Work Logs




Name	Description
Cavins Group Environmental	Cavins technician added 5 gallons of diesel fuel to boom lift. Assisted envelope consultants with moving the boom lift, also assisted the consultants with the Oklahoma Roofers and Glass Pro glazers.
Total	



## General Notes

### 1. Equipment On Site












### 2. Oklahoma Roofing





### 3. Proglass








**4. Diesel Fuel Added To Lift  
5 - Gallons**



**5. Boom Lift Move**





- 6. First Floor - Main Area: Equipment**
  - 3 - Air Scrubbers
  - 1 - 25' Extension Cord
- 7. Second Floor - Main Area: Equipment**
  - 1 - Air Scrubber
  - 1 - 25' Extension Cord
- 8. Third Floor - Main Area: Equipment**
  - 1 - Air Scrubber
  - 1 - 50' Extension Cord