



1839 Atchison Drive
Norman
OK
USA

Water intrusion/structural drying - 08/11/24

Claim Id

Norman Public Library - Central,
8.11.24

Date of Loss

Aug 11, 2024

Date Claim Created

Aug 11, 2024

Address

103 West Acres Street, Norman, OK,
USA

Policyholder Name


City Of Norman

General Notes

8.11.24 - Total Equipment Counts

21 DHUs
50 Axial fans
8 50" extension cords

8.14.24 - Antimicrobial treatment



8.12.24- Total equipment counts

7 DHUs
15 Axial fans



Stairway










Overview Photos: Stairway













Room Notes: Stairway







8.11.24 - Thermal imaging














8.11.24 - Equipment counts

4 DHUs
8 Axial fans
7 50' extension cords





8.11.24 - Overall equipment




8.12.14 - Equipment counts

- 4 DHUs
- 8 Axial fans
- 7 50' extension cords










8.12.24 - Overall equipment




8.12.24 - Thermal imaging







8.12.24 - Equipment removal





Oklahoma 301

Overview Photos: Oklahoma 301



Room Notes: Oklahoma 301


8.11.24 - Thermal imaging








Pioneer 305








Overview Photos: Pioneer 305













Room Notes: Pioneer 305

8.11.24 - Thermal imaging











8.11.24 - Equipment counts

2 DHUs
4 Axial fans





8.11.24 - Overall equipment





8.12.24 - Equipment counts

2 DHUs
4 Axial fans





8.12.24 - Overall equipment



8.12.24 - Thermal imaging






8.12.24 - Equipment removal



Drying standard met





3rd Floor Common Area







Overview Photos: 3rd Floor Common Area



Room Notes: 3rd Floor Common Area

8.11.24 - Thermal imaging






8.11.24 - Equipment counts

- 1 DHU
- 3 Axial fans



8.11.24 - Overall equipment



8.12.24 - Equipment counts


1 DHU
3 Axial fans



8.12.24 - Overall equipment



8.12.24 - Thermal imaging



**8.12.24 - Equipment
removal: Drying standard
met**




Research 314



Overview Photos: Research 314



Room Notes: Research 314

8.11.24 - Thermal imaging





8.11.24 - Equipment counts

- 1 DHU
- 2 Axial fans



8.11.24 - Overall equipment



8.12.24 - Equipment counts

- 1 DHU

2 Axial fans



8.12.24 - Overall equipment



8.12.24 - Thermal imaging



**8.12.24 - Equipment
removal: Drying standard
met**



2nd Floor Common Area

Overview Photos: 2nd Floor Common Area


















Photo 1









Room Notes: 2nd Floor Common Area

8.11.24 - Thermal imaging















8.11.24 - Equipment counts

4 DHUs
14 Axial fans
1 50' extension cord







8.11.24 - Overall equipment



8.12.24 - Equipment counts

- 4 DHUs
- 14 Axial fans
- 1 50" extension cord











8.12.24 - Overall equipment




8.12.24 - Thermal imaging








8.12.24 - Equipment removed



8.13.24 - Thermal imaging





8.13.24 - Equipment counts

2 DHUs
4 Axial fans



8.13.24 - Overall equipment



8.13.24 - Equipment removal



Drying standard met

Staff Only 201A






Overview Photos: Staff Only 201A



Photo 1


Room Notes: Staff Only 201A

8.11.24 - Thermal imaging




8.11.24 - Equipment counts

2 DHUs
4 Axial fans



8.11.24 - Overall equipment



8.11.24 - Ceiling tile removal





8.12.24 - Equipment counts

2 DHUs
4 Axial fans





8.12.24 - Overall equipment




8.12.24 - Thermal imaging





8.12.24 - Equipment removal




8.13.24 - Equipment counts


1 DHU
2 Axial fans



8.13.24 - Overall equipment



8.13.24 - Equipment removal: Drying standard met



8.13.24 - Thermal imaging






Study Room 231

Overview Photos: Study Room 231



Room Notes: Study Room 231

8.11.24 - Thermal imaging



8.11.24 - Equipment counts





1 DHU
1 Axial fan

8.11.24 - Overall equipment




8.12.24 - Thermal imaging






8.13.24 - Thermal imaging



8.12.24 - Equipment counts

- 1 DHU
- 2 Axial fans



8.12.24 - Overall equipment



8.13.24 - Equipment counts


- 1 DHU
- 2 Axial fans



8.13.24 - Overall equipment



8.13.24 - Equipment removal



Study Room 324

Overview Photos: Study Room 324



Photo 1


Room Notes: Study Room 324

8.11.24 - Thermal imaging



Staff Only 115

Overview Photos: Staff Only 115



Room Notes: Staff Only 115

8.11.24 - Equipment counts




1 DHU
3 Axial fans






8.11.24 - Overall equipment



















8.11.24 - ceiling tile removal






8.11.24 - Thermal imaging











8.12.24 - Thermal imaging





8.12.24 - Equipment counts


- 1 DHU
- 3 Axial fans



8.12.24 - Overall equipment



8.13.24 - Thermal imaging




8.13.24 - Equipment counts


1 DHU
3 Axial fans



8.13.24 - Overall equipment




8.13.24 - Equipment removal: Drying standard met



Sketches: Staff Only 115

Staff only 115



Childrens Area

Overview Photos: Childrens Area




Photo 1

Room Notes: Childrens Area

8.11.24 - Equipment counts

3 DHUs
6 Axial fans






















8.11.24 - Overall equipment








8.11.24 - Thermal imaging










8.12.24 - Thermal imaging




8.12.24 - Equipment counts

3 DHUs
6 Axial fans



8.12.24 - Overall equipment




8.12.24 - Equipment removal

Drying standard met



Sketches: Childrens Area

Children's area




1st floor common area

Overview Photos: 1st floor common area









Vestibule

Overview Photos: Vestibule



Room Notes: Vestibule

8.11.24 - Thermal imaging



8.11.24 - Ceiling tile removal






Staff Only 212

Overview Photos: Staff Only 212



Room Notes: Staff Only 212

8.11.24 - Thermal imaging



8.11.24 - Equipment counts

1 DHU
2 Axial fans




8.11.24 - Overall equipment



8.11.24 - Ceiling tile removal



8.12.24 - Thermal imaging



8.12.24 - Equipment counts

- 1 DHU
- 2 Axial fans



8.12.24 - Overall equipment



8.13.24 - Equipment counts


- 1 DHU
- 2 Axial fans



8.13.24 - Overall equipment



8.13.24 - Thermal imaging




8.13.24 - Equipment removal: Drying standard met








Study Room 233


Overview Photos: Study Room 233



Room Notes: Study Room 233


8.11.24 - Thermal imaging





8.11.24 - Equipment counts

- 1 DHU
- 2 Axial fans



8.11.24 - Overall equipment



8.12.24 - Equipment counts



- 1 DHU
- 2 Axial fans




8.12.24 - Overall equipment




8.12.24 - Thermal imaging



8.13.24 - Thermal imaging





8.13.24 - Equipment counts

- 1 DHU
- 2 Axial fans



8.13.24 - Overall equipment



8.13.24 - Equipment removal: Drying standard met

